

Inspection Photos
Location Name: ROUSE-USX A-66N64W/5NWNW
Location #: 306456



Photo #1

Rouse-USX A 5-19 (123-24697) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)



Photo #2

Rouse-USX A 5-19 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Site safety signage



Inspection Photos

Location Name: ROUSE-USX A-66N64W/5NWNW
Location #: 306456



Photo #3
Rouse-USX A 5-19 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Wellsite entrance

A photograph of a job safety analysis (JSA) form. The form is titled "job safety analysis (JSA) form" and "roles, contingency and response". It includes sections for "tools", "stop work authority", "PIC pre-job checklist", "last minute risk assessment", and "after action review". The form is filled out with handwritten information, including the location name "ROUSE-USX A 5-19", the date "1-5-24", and the PIC name "Edgar Chavez". The form also includes a "NEAREST MEDICAL CENTER" section and a "Work Crew Sign-In" section. The text "Colorado Energy & Carbon Management Commission" and "2024-01-05 13:20" is visible in the bottom right corner of the photo.

Photo #4
Rouse-USX A 5-19 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
JSA: 2024-01-05



Inspection Photos

Location Name: ROUSE-USX A-66N64W/5NWNW

Location #: 306456



Photo #5

Rouse-USX A 5-19 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)

Battery sign



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources