

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2024

Submitted Date:

01/06/2024

Document Number:

708902714

FIELD INSPECTION FORMLoc ID 335236 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211197	WELL	PR	03/27/1995	GW	045-06956	CLOUGH RMV 25-20	PR
260583	WELL	PR	06/09/2001	GW	045-07874	CLOUGH RWF 433-20	PR

General Comment:**CECMC Inspection Report Summary**

On 01/04/2024 at approximately 14:58 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 25-20 Pad.

Location # 335236 in Garfield County Colorado.

Please refer to inspection 708902318 conducted on 11/21/2023, previous corrective actions have been completed.

Location is within High Priority/Density Habitat areas.

Location is approximately 68 yards from a drainage that contributes to the Colorado River.

While there, I observed normal production operations.

This is a summary of inspection report.

Shared facilities with the CLOUGH RMV 211-20 pad, location # 335284

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign legible at this time but extremely weathered & may need to be replaced in the near future.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth						
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity) 80 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	211197	Type:	WELL	API Number:	045-06956	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260583	Type:	WELL	API Number:	045-07874	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in some areas
Gravel						Sparse to none in areas
Berms						
		Culverts				
		Ditches				
Tracking Pad						Gravel based VTC at entrance to wellheads
		Compaction				
		Gravel				Sparse to none in some sections

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Shared facilities with the CLOUGH RMV 211-20 pad, location # 335284	smelserw	01/06/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902715	Inspection 708902714 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383976
708902716	Inspection 708902714 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6383977