

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 1 loc pic



Photo 2 impacted tracking pad

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 3 loc pic and dead weeds



Photo 4 electric disconnect.

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 5 well head



Photo 6 well head

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 7 Hoz Sep



Photo 8 Dead weeds on location.

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 9 Meter run



Photo 10 dead weeds on location

Inspection Photos

Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo 11 TNK BTRY sign



Photo 12 Crude oil tank stained soil and what appears to be mechanical issues with the 2 in piping and rusted bolts on inspection hatch.

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318 253



Photo13 stained soil under crude oil load out lines and what appears to be mechanical issue with 2 in piping



Photo 14 ECD