

Inspection Photos
Location Name: Champlin 367 Amoco #1
Location ID: 318431



Photo 1 loc pic



Photo 2 Well head. No sign DEAD WEEDS DEBRIS

Inspection Photos
Location Name: Champlin 367 Amoco #1
Location ID: 318431



Photo 3 What appears to be contaminated soil and unused equipment



Photo 4 Produced water vault. DEBRIE

Inspection Photos
Location Name: Champlin 367 Amoco #1
Location ID: 318431



Photo 5 TNK BTRY Battery sign peeling need to be replaced along with NFPA placards DEAD WEEDS DEBRIS



Photo 6 DEAD WEEDS DEBRIS

Inspection Photos
Location Name: Champlin 367 Amoco #1
Location ID: 318431



Photo 7 Meter house DEAD WEEDS DEBRIS. Unused equipment (cattle panels), Meter tube has been LOTO since 2020 and pined pulled house considered unused equipment.




Photo 8 Meter calibration card has not been calibrated since 2006

Inspection Photos
Location Name: Champlin 367 Amoco #1
Location ID: 318431



Photo 9 Meter tube LOTO and pined pulled.