

Final Reclamation Inspection

December 28th, 2023

Operator: Simcoe LLC - 10749

Location ID: 333703

Inspection Document #: 714000278

La Plata County, CO

Township: NESW 9 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ralph Downing A2, A4
Location ID: 333703



Photo 1. View of the well disturbance from the entrance facing center.



API #: 067-08499, 09236

Inspection Photos

Location Name: Ralph Downing A2, A4

Location ID: 333703



Photo 2. View of rill/gully erosion forming at the access point.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08499, 09236

Inspection Photos

Location Name: Ralph Downing A2, A4

Location ID: 333703



Photo 3. View of additional rill/gully erosion forming on the eastern edge of the disturbance.

API #: 067-08499, 09236



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ralph Downing A2, A4
Location ID: 333703



Photo 4. View of unused equipment/debris observed in the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08499, 09236

Inspection Photos

Location Name: Ralph Downing A2, A4

Location ID: 333703



Photo 5. View of musk thistles observed in various locations throughout the disturbance.

API #: 067-08499, 09236



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

12/28/23
+37.202116,-107.727485
303° NW



Photo 6. Reference area comprised of western wheatgrass, sagebrush and juniper.