

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2024

Submitted Date:

01/08/2024

Document Number:

707901244**FIELD INSPECTION FORM**Loc ID 318431 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241284	WELL	SI	10/01/2023	GW	123-09072	CHAMPLIN 367 AMOCO 1	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	NFPA placards faded and peeling. Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/08/2024
Type	BATTERY		
Comment:	Battery sign peeling and not readable.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	02/08/2024
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/08/2024

**Emergency Contact Number:**Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	What appears to be contaminated soil on plastic next to well head		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	02/08/2024
Type	UNUSED EQUIPMENT		
Comment:	Parts around well head and cattle pannels in front of meter house. Meter house is LOTO and pin has been removed meter house is considered unused equipment.		
Corrective Action:	Comply with rule 606	Date:	02/08/2024
Type	DEBRIS		
Comment:	Dead weeds on site and around equipment		
Corrective Action:	Comply with rule 606	Date:	02/08/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment: <a href="#">Meter last calibration date 2006</a>			
Corrective Action: <a href="#">Calibrate gas metering equipment annually to comply with rule 430.d.(1).</a>		Date: <a href="#">02/08/2024</a>	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity) 40		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares containment with crude oil tanks</a>				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241284 Type: WELL API Number: 123-09072 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI Flow line valves appear to be in the closed position at time of inspection.Corrective Action:  Date: **BradenHead**Date of Last Brhd Test: 09/05/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: **COGCC Comments**

Comment	User	Date
ECMC Inspection Report Summary On January 3, 2024 at approximately 11:30 AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Champlin 367 Amoco #1 Operator: KP Kauffman API#: 123-09072 County: Weld While there, I observed a Shut in well head and facility. During this inspection the following possible compliance issues were observed: Debris: Rule 606 Corrective action date of 2-8-24 See photos 2,4,5,6,7 Tank Sign: Rule 605 e Corrective action date of 2-8-24 See photo 5 Well head sign: Rule 605 d Corrective action date of 2-8-24 See photo 2 Stained soil: Rule 905 e Corrective action date of 2-8-24 see photo 3 Unused equipment: Rule 606 Corrective action date of 2-8-24 See photos 3,7 Placards: Rule 605 e Corrective action date of 2-8-24 See photo 5 Meter calibration: Rule 430 d (1) Corrective action date of 2-8-24 See photo 8 Weather conditions: clear A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.	silverr	01/08/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
707901245	loc pic	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384741">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384741</a>