

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2024

Submitted Date:

01/02/2024

Document Number:

696305628**FIELD INSPECTION FORM**Loc ID 302389 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298430	WELL	TA	05/26/2020	OW	123-29060	Wells Ranch USX AA 13-08	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Unused Secondary Containment at Wellsite; see photos		
Corrective Action:	Comply with Rule 606	Date:	01/16/2024
Type	UNUSED EQUIPMENT		
Comment:	3 - 1" Risers at Wellhead not OOSLAT; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	01/05/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe Fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	TA - Well has been disconnected from Flowline		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 298430

Type: WELL

API Number: 123-29060

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: TA - 05.26.2020. Form 6A 403118488 dated 08.16.2022 with a Plug Due Date of 12.31.2030

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine Field Inspection. 3 - 1" Unmarked Risers at Wellsite. Unused Secondary Containment	petrie	01/02/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403642574	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6379048
696305629	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6379020