


Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Jan 8, 2024 at 12:45:36 PM
CO



Jan 8, 2024 at 12:48:58 PM
CO

Photo # 2030 From entrance to location

Photo # 2031 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2032 Location



Photo # 2033 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Jan 8, 2024 at 12:47:30 PM
CO

Photo # 2034 Location



Jan 8, 2024 at 12:48:12 PM
CO

Photo # 2035 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2036 Location



Photo # 2037 Flowline heating insulation open ended



Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2038 Hole in flowline heating insulation/wildlife hazard