

Final Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313646

Inspection Document #: 708200846

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 1. Taken from the eastern portion of the access road, facing east. The access roads do not appear to have been reclaimed as they are not contoured/graded to reflect pre-disturbance/reference area topography. Additional reclamation activities are required.

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 2. Taken south of the location, facing north. Photo illustrates that the access road and former location have not been regraded or contoured to reflect pre-disturbance conditions.

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 3. Google Earth aerial imagery taken circa 09/2023. Photo illustrates access roads, highlighted in red, that have not been reclaimed and will require such activities per Rule 1004.

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 4. Taken west of the location. The former well location is not progressing towards Rule 1004 standards and regulations as the location is predominantly bare/exposed soils and the access road which has not been reclaimed.

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 5. Taken from the northern portion of the former well location; see comments in Photo 4.

Inspection Photos
Location Name: Sand River #16
Location ID: 313646



Photo 6. Taken from the eastern portion of the former well location; see comments in Photo 4.