

Interim Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 393493

Inspection Document #: 708200847

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 1. Taken from the southeast corner of the location. Unused equipment and unstabilized production areas pictured.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photos 2 & 3. Unused equipment and debris located next to facility.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 4. Erosion degradation occurring on pit berms.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493




Photo 5. Taken near the southeast corner of the pit. Photo illustrates that there are no apparent stormwater control measures around the perimeter of the location and pit. Also pictured, undesirable vegetation (e.g. russian thistle) that does not appear to have been managed for.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 6. Taken southeast from the pit. Blow sand accumulations were observed southeast of the pit, indicating wind erosion from unstabilized production areas.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 7. Taken from the east side of the pit. Photo illustrates that pit berms are eroding and the production areas are not properly stabilized.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493




Photo 8. Northeast corner of the pit. No apparent perimeter stormwater controls and undesirable vegetation (e.g. russian thistle) observed.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 9. Taken from the northwest corner of the pit. Photo illustrates no apparent stormwater controls that would prevent the sediment transport (pictured by red arrow) from leaving the location. Additional stormwater controls are needed for the location. Also pictured, undesirable vegetation (russian thistle).

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493




Photo 10. Western side of pit. Pit berms are severely eroded and require maintenance and additional stormwater controls to prevent sediment transport outside of the fenced areas.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 11. Tank label at produced water tank is not legible.

Inspection Photos
Location Name: Sand River 61N56W
Location ID: 393493



Photo 12. Overview of pit from the southwest corner. The pit is experiencing severe erosion degradation.