

# Inspection Photos

Loc: 384227

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/10/2024

County: KIOWA



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north near the location. This area has been fenced and excavation has occurred of impacted soils from historic release.



## Inspection Photos



**Photo 2.** There has been excavation and removal of impacted soils



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 384227 | Date: 1/10/2024

## Inspection Photos



**Photo 3.** Facing northwest at the abandoned wellsite location. The sandy soils have not revegetated and need to be seeded and reclaimed.



## Inspection Photos



**Photo 4.** Facing southwest near the abandoned wellsite is abandoned flowline cellar that needs to be removed. Lat/Long:38.42706, -102.46211.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Loc: 384227 | Date: 1/10/2024

## Inspection Photos



**Photo 5.** Facing east at the abandoned wellsite location. The sandy soils have not revegetated and need to be seeded and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 384227 | Date: 1/10/2024

## Inspection Photos



**Photo 6.** Facing southeast at the location. This area has not revegetated and needs to be seeded and stabilized. There is a 1 wire electric fence installed.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 384227 | Date: 1/10/2024

## Inspection Photos



**Photo 7.** This is a 1990's aerial image of the wellsite. The yellow arrow shows the flowline cellar, red arrow shows where impacted soil has been excavated.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Loc: 384227 | Date: 1/10/2024