

Inspection Photos

Loc: 427573

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2024

County: KIOWA



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 1. Facing east along the access road. There is deep ruts along this area of the road which is not stabilized.



Inspection Photos



Photo 2. Facing east along the road near the location. This area is swalled and the road has been widened due to vehicle driving avoid this area during wet conditions..



Inspection Photos



Photo 3. Facing southeast toward the wellsite.



Inspection Photos



Photo 4. There is undesirable weed debris along the fence line that needs to be removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 427573 | Date: 1/10/2024

Inspection Photos



Photo 5. The berm around the tanks are inadequate to contain a spill.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 427573 | Date: 1/10/2024

Inspection Photos



Photo 6. Facing toward the well head and separator.



Inspection Photos



Photo 7. There is oil containers and oil fluid stored in this metal box that needs to be removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 427573 | Date: 1/10/2024

Inspection Photos



Photo 8. Facing toward the pumpjack. Unused pipe and containers need to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 427573 | Date: 1/10/2024

Inspection Photos



Photo 9. There are oil fluids and empty containers in the containment at red arrow that needs to be cleaned up and removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 427573 | Date: 1/10/2024