

# Inspection Photos

Loc: 417910

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/10/2024

County: KIOWA



Inspection Photos



**Photo 1.** Facing north toward the wellsite. The wind sock is no longer present.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 417910 | Date: 1/10/2024

Inspection Photos



**Photo 2.** There are unused parts laying on the ground next to the pumpjack.



## Inspection Photos



**Photo 3.** There is parts and trash debris inside this broken container that needs to be removed..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 417910 | Date: 1/10/2024

Inspection Photos



**Photo 4.** There is oil stained soil next to the engine pumpjack that needs to be cleaned up.



## Inspection Photos



**Photo 5.** There are various and empty containers inside the containment that need to be thrown away..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 417910 | Date: 1/10/2024

Inspection Photos



**Photo 6.** One of the empty oil containers has blown at into the field.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc: 417910 | Date: 1/10/2024