

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2024

Submitted Date:

01/12/2024

Document Number:

713600611

**FIELD INSPECTION FORM**

Loc ID 417910 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10330  
Name of Operator: INVESTMENT EQUIPMENT LLC  
Address: 558 CASTLE PINES PKWY UNIT B-4  
City: CASTLE PINES State: CO Zip: 80108

**Findings:**

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bongers, Brent		bbongers@impetroresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417910	LOCATION	AC			-	TRADE WINDS 1-21	RI

**General Comment:**

This is a location inspection of the TRADE WINDS #1-21 wellsite.  
See attached photos and additional details within this report.

The date of discovery is given for all new corrective action dates. It is ECMC's expectation that Operators are in compliance with ECMC rules at all times. Therefore, No extended CA dates are applied and the corrective action will remain out of compliance until completed.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	The H2S wind sock needs to be replaced.		
Corrective Action:	Install required equipment to comply with Rule 612.e.	Date:	01/10/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	There are empty oil containers and varios parts stored at by the pumpjack that are unused and need to be removed. One of the oil containers has blown out into the field, There are also unused pumpjack that need to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	01/10/2024

Overall Good:

**Spills:**

Type	Area	Volume		
Lube Oil	Pump Jack			
Comment:	There is oil stained soil next to the engine pumpjackthat needs to be cleaned up.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.		Date:	01/10/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600612	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6391986">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6391986</a>

