

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2024

Submitted Date:

01/08/2024

Document Number:

702402808**FIELD INSPECTION FORM**Loc ID 321347 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206754	WELL	SI	09/01/2023	GW	013-06249	ALMQUIST 2-35	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign is peeling		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	03/08/2024

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type			
Comment:	farmers tarp has been blown next to the well fence.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Ag panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	baarbless wire		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	exposed at surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	automation & Fugitive gas recovery device		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	48 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shres containment with crude tank				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.089940,-105.088440	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					

Corrective Action:		Date:	
Wells Served By Facilities Above			
API Number		AirsID	
013-06249		API Number AirsID	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	206754	Type:	WELL	API Number:	013-06249	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment: SI									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 06/06/2023									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 12									
Fluid Type: NONE									
End Surf Csg Pressure: 0									
Comment:									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Monday 1-8-2024 at approximately 1505hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: Civitas/Extraction Oil & Gas Inc.</p> <p>Location name: Almquist 62N69W 35SWSW</p> <p>Location ID # 321347</p> <p>Well Name: Almquist 2-35</p> <p>API # 05-013-06249</p> <p>County: Boulder</p> <p>Weather: Clear, windy & cold.</p> <p>Location: Dry</p> <p>While there, I observed a wellsite & tank battery, SI at the time of the inspection.</p> <p>During this inspection, I observed the following possible compliance issues:</p> <p>605.g Signs general condition: CA date 3-8-2024</p> <p>See attached photos.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	01/08/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403648341	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6385677
702402809	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6385671