

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2024

Submitted Date:

01/08/2024

Document Number:

707901244**FIELD INSPECTION FORM**Loc ID 318431 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241284	WELL	SI	10/01/2023	GW	123-09072	CHAMPLIN 367 AMOCO 1	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placards faded and peeling. Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/08/2024
Type	BATTERY		
Comment:	Battery sign peeling and not readable.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	02/08/2024
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s)		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/08/2024

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Parts around well head and cattle pannels in front of meter house. Meter house is LOTO and pin has been removed meter house is considered unused equipment.		
Corrective Action:	Comply with rule 606	Date:	02/08/2024
Type	DEBRIS		
Comment:	Dead weeds on site and around equipment		
Corrective Action:	Comply with rule 606	Date:	02/08/2024
Type	OTHER		
Comment:	What appears to be contaminated soil on plastic next to well head		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	02/08/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter last calibration date 2006		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/08/2024
Type: Bradenhead	# 1		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	40	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 241284 Type: WELL API Number: 123-09072 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI Flow line valves appear to be in the closed position at time of inspection.Corrective Action:  Date: **BradenHead**Date of Last Brhd Test: 09/05/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action:  Date: **COGCC Comments**

Comment	User	Date
ECMC Inspection Report Summary On January 3, 2024 at approximately 11:30 AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Champlin 367 Amoco #1 Operator: KP Kauffman API#: 123-09072 County: Weld While there, I observed a Shut in well head and facility. During this inspection the following possible compliance issues were observed: Debris: Rule 606 Corrective action date of 2-8-24 See photos 2,4,5,6,7 Tank Sign: Rule 605 e Corrective action date of 2-8-24 See photo 5 Well head sign: Rule 605 d Corrective action date of 2-8-24 See photo 2 Stained soil: Rule 905 e Corrective action date of 2-8-24 see photo 3 Unused equipment: Rule 606 Corrective action date of 2-8-24 See photos 3,7 Placards: Rule 605 e Corrective action date of 2-8-24 See photo 5 Meter calibration: Rule 430 d (1) Corrective action date of 2-8-24 See photo 8 Weather conditions: clear A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.	silverr	01/08/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403647519	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384798">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384798</a>
707901245	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384741">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6384741</a>