

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2969 From entrance to location



Photo # 2970 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2971 Location



Photo # 2972 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2973 Location




Photo # 2974 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2037 From inspection 708902741 flowline heating insulation open ended



Photo # 2975 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2038 From inspection 708902741 hole in flowline heating insulation/wildlife hazard



Photo # 2976 Hole in flowline heating insulation/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL 30-6 (PG30) Pad

Location #: 334657



Photo # 2977 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources