

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOAN STREET

DENVER, COLORADO 80203

WILLIAM R. SMITH
Director

FRANK J. PIRO
Deputy Director

(303) 866-3531



99999999

D. LAMM
Governor

March 6, 1985

087-05628

Mr. Don Lutkey
Okmar Oil Co.
633 17th St. #2160
Denver, CO 80202

Re: Huey #16 SE NW Sec. 29 - 2N - 56W

Dear Don;

This letter is to reiterate our position with regard to our conversation on March 4, 1985 concerning the Huey #16 in the Burr Field. Since the pressure bleed off during the mechanical integrity test conducted on February 28, 1985 was outside of our normal allowable limit, but still within a reasonable range, we have decided in lieu of working the well over at present, that you are to monitor and report monthly the bradenhead pressure on our Form 14. You will also be required to retest the well within a one year period. This should allow for either stabilization of the wellbore condition or show just cause to work over the well and take corrective action.

If you have any questions or need clarification of our position, please feel free to call me.

Very truly yours,

Larry Robbins
Petroleum Engineer

LR/ck



00048317