

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788

Inspection Doc: 696205535

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 1: Photos 1-2 taken from the southern working pad surface of the Location. Photos provide an overview of the Location from southwest, west, north to northeast. Photos also examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 2: Photos taken from the east end of the Location. Photos provide an overview of the Location from southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 3: Photos taken examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 4: Photos taken from the slopes behind the tank battery facility. Stormwater and erosion control BMPs are missing or insufficient. Soil are bare and erosion degradation is apparent. Sediment eroded from the slopes are deposited within a ditch, which discharges off-site.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



January 16, 2024

Photo 5: Photo taken from the north end of the Location; stormwater runoff from the working pad surface is resulting in erosion and degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 6: Photo taken from the stormwater outlet on the north end of the Location, near the entrance. Outlet has not been installed or maintained in accordance with good engineering practices; stormwater has eroded areas of the control beneath/around the rip-rap material; geotextile lining in conjunction with rip-rap not observed per good engineering practices.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335788



Photo 7: Photos examples of the interim areas of the Location. Slopes (photo right) may require additional revegetation efforts to ensure uniform establishment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources