

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174

Inspection Doc: 696205539

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 1: Photos taken from the west end of the well's working pad surface of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 3: Photos examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 4: Photos taken from the eastern working pad surface of the well site. Photos examples of interim areas not progressing towards 1003 standards. Photos also examples showing stormwater and erosion control BMPs are missing or insufficient; BMPs to minimize erosion and degradation within the interim areas are inadequate; erosion log (wattles) has not been installed or maintained per good engineering practices resulting stormwater cutting beneath the BMP and degradation to the ditch.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 5: Photos taken from the eastern interim areas of the Location. Photos examples of interim areas not progressing towards 1003 standards. Photos also examples showing stormwater and erosion control BMPs are missing or insufficient; BMPs to minimize erosion and degradation within the interim areas are inadequate. Additional reclamation effort and stormwater management required in these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 6: Erosion logs have not been installed or maintained in accordance with good engineering practices; stormwater has cut under the BMP resulting in concentrated flows and erosion degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 7: Photo example of erosion logs that have not been maintained in proper functioning condition. Erosion logs implemented appear to also be made of plastic material; this is an improper control, considered trash/debris and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 8: Photos taken from the western interim areas of the well site. Photos examples of interim areas not progressing towards 1003 standards. Photos also examples showing stormwater and erosion control BMPs are missing or insufficient; BMPs to minimize erosion and degradation within the interim areas are inadequate. Additional reclamation effort and stormwater management required in these areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335174



Photo 9: Photo taken from the tank battery facility. Photo shows erosion degradation due to stormwater runoff. Photo also shows fence at battery in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources