

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/09/2024

Submitted Date:

01/12/2024

Document Number:

710100125

**FIELD INSPECTION FORM**

Loc ID 336314 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**  
 OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**Findings:**  
9 Number of Comments  
4 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Oxy All Inspections		ECMCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287078	WELL	PA	03/28/2023	OW	123-27367	JUNCTION 22-2	PA
287135	WELL	PA	03/23/2023	GW	123-27377	JUNCTION 12-2	PA
287136	WELL	PA	12/11/2017	GW	123-27376	JUNCTION 11-2	PA
484183	SPILL OR RELEASE	CL	04/03/2023		-	Junction 11, 12, 22-2 O SA Facility	EI
485125	SPILL OR RELEASE	CL	09/15/2023		-	Junction 11, 12, 22-2 O SA Facility	EI
485236	SPILL OR RELEASE	CL	09/15/2023		-	Junction 11, 12, 22-2 O SA Facility	EI

**General Comment:**

ECMC Environmental Protection Specialist, Laurel Anderson, performed an Environmental Field Inspection on January 9th, 2024, for the following:  
 -JUNCTION-62N68W 2NWSW location (Location ID 336314)  
 -JUNCTION 22-2 well (API 123-27367)  
 -JUNCTION 12-2 well (API 123-27377)  
 -JUNCTION 11-2 well (API 123-27376)  
 -Remediation Project #27343  
 -Remediation Project #27339  
 -Spill/Release Point ID 484183  
 -Spill/Release Point ID 485125  
 -Spill/Release Point ID 485236

Photos attached document site conditions at the time of this inspection.  
 Any corrective actions from previous inspections and/or conditions of approval from previous forms that have not been fully addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Location requires maintenance. Portable toilet on location is not properly anchored and has been tipped over.

Corrective Action: Comply with ECMC Rule 1002.f.(2)D. perform self-inspection, maintenance and good house keeping procedures and schedules.

Date: 01/26/2024

Type

WEEDS

Comment: Weeds present throughout location.

Corrective Action: Comply with Rule 606 and Rule 1003.f.

Date: 01/26/2024

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Location Construction**

Location ID: 336314 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** Netting over remedial excavations has been installed but has since begun to fall.

Corrective Action: Operator shall repair and maintain wildlife protection equipment.

Date: 01/26/2024

**Comment:** Per CA on Doc #710100055:  
"-Vehicle trackout was observed onto CR 2450. Trackout pad requires maintenance  
-No BMPs are in place to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite and site degradation. Northern perimeter of the pad is not stabilized and is showing signs of rill erosion and transport of sediment/pad material off location.  
-Stormwater run-in to the open excavation has resulted in rill erosion, wall destabilization and transport and accumulation of stormwater and sediment within the open excavations."  
Trackout was not observed at the time of this inspection.

**Corrective Action:** Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.  
  
Ongoing issue - Corrective action due date back-dated to due date required on previous inspection Doc #710100055.

Date: 10/10/2023

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 287078 Type: WELL API Number: 123-27367 Status: PA Insp. Status: PA

Facility ID: 287135 Type: WELL API Number: 123-27377 Status: PA Insp. Status: PA

Facility ID: 287136 Type: WELL API Number: 123-27376 Status: PA Insp. Status: PA

Facility ID: 484183 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 485125 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Facility ID: 485236 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: Remediation Project 27339 remains open at the site.  
 Remediation Project 27343 remains open at the site.  
 Remedial excavations remain open with fencing.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**COGCC Comments**

Comment	User	Date
BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Operators shall employ BMPs, as necessary to comply with this rule, at all oil and gas locations, including, but not limited to, well pads, soil stock piles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on sitespecific conditions, operators shall implement BMPs in accordance with good engineering practices.	andersoln	01/12/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403652952	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6390899">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6390899</a>
710100126	Photo Documentation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6390890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6390890</a>