



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	metal panel		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	#		corrective date
Comment:	pipesd to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243648 Type: WELL API Number: 123-11440 Status: SI Insp. Status: SI

**BradenHead**

Date of Last Brhd Test: 08/08/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: None  
 End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection..... during Rig MIRU Form 42 for plugging well</a>	kesterm	01/18/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300537	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6399391">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6399391</a>