

Final Reclamation and Stormwater Inspection

Date: 1/11/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 332995

Inspection Document #: 713900278

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Brattain L12-6JI
Location ID: 332995



Photo 1. The photo was taken at the well location facing North. The photo illustrates the well location is dominated by russian thistle.



Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: Brattain L12-6JI
Location ID: 332995



Photo 3. The photo was taken at the well location facing South.
Refer to the comment for photo 1.



Photo 4. The photo was taken at the well location facing West.
Refer to the comment for photo 1.

Inspection Photos
Location Name: Brattain L12-6Jl
Location ID: 332995



Photo 5. The photo was taken at the well location facing South. The photo illustrates that gravel still remains at the well location.



Photo 6. The photo was taken at the well location facing East. The photo illustrates that there is a stand of Musk thistle at the well location.

Inspection Photos
Location Name: Brattain L12-6Jl
Location ID: 332995



Photo 7. The reference photo was taken near the well location facing Southeast.