

Inspection Photos

Loc: 438617

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/18/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the gas treatment facility.



Inspection Photos



Photo 2. Photo 2. There is an unused compressor stored on location that need to be removed. The compressor engine has various unconnected parts and does not appear to be functional. Previous corrective action is not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 3. Facing toward the open top tank. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. There is no signage on the tank. Previous corrective action is not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 5. The netting on the open top tank has come uncovered on the edges which wildlife could gain entry.



Inspection Photos



Photo 6. There is a white stained substance around the base of the open top tank. There is a new tank installed but the labeling is faded on the container so contents are unknown.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 7. There is equipment not maintained and weeds grown around the equipment. Door has fallen off this shed. Previous corrective action is not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 8. There is an open top tank at the east side of the location. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. The signage has faded. Previous corrective action is not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 9. There is liquid in the tank and the netting is in disrepair.



Inspection Photos



Photo 10. Facing west toward the location. There is a plastic liner debris at east side of the location that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 11. There is unused supplies and a black barrels with no labeling. There are weeds and vegetation around the equipment which is a fire hazard. Previous corrective action is not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024

Inspection Photos



Photo 12. Facing east toward the gas treatment facility.



Inspection Photos



Photo 13. Photo taken during previous inspection. Facing east at the south side of the location. The surrounding disturbance area has areas that are bare of vegetation that need to be reclaimed per Rule 1003.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:438617 | Date: 1/18/2024