

Inspection Photos

Loc: 320981

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/18/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. Facing toward the open top tank. There is not secondary containment at the tank and there is oily fluids inside the tank.



Inspection Photos



Photo 3. There is an used pipe riser at red arrow .



Inspection Photos



January 18, 2024
+37.357735,-102.374040

Photo 4. The sign at the wellhead is faded and not legible.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320981 | Date: 1/18/2024