

Inspection Photos

Loc: 320975

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/18/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:320975 | Date: 1/18/2024

Inspection Photos



Photo 2. Facing toward the open top tank. There is not secondary containment at the tank and there is oily fluids inside the tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320975 | Date: 1/18/2024

Inspection Photos



Photo 3. Facing toward the well. The gate has fallen over and is laying in the snow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:320975 | Date: 1/18/2024