

Interim Reclamation and Stormwater Inspection

Date:01/12/2024

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 427480

Inspection Document #: 708200877

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 1. Undesirable vegetation observed at the location's entrance.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



1/12/24, 11:06 AM
97° E
ECMC

Photo 2. Erosion degradation at cattle guard.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 3. Erosion degradation and undesirable vegetation along the access road.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 4. South side of production areas. Undesirable vegetation (e.g. russian thistle, kochia, crested wheatgrass, smooth brome) observed throughout the interim areas.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 5. Unused equipment observed between the tank battery and combustor on the southwest corner of the production area.



Photo 6. Stained soil at compressor station.



Photo 7. Stained soil at compressor station.



Photo 8. Tank signs/labels not legible (peeling, faded, cracked).

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 9. Tank signs/labels not legible (peeling, faded, cracked).



Photo 10. Opposite side of Photo 9. Tank signs/labels not legible (peeling, faded, cracked).

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 11. Tank signs/labels not legible (peeling, faded, cracked).



Photo 12. Tank signs/labels not legible (peeling, faded, cracked).

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 13. Stained soil at tank battery.



Photo 14. Stained soil at tank battery.



Photo 15. Stained soil at tank battery.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 16. Taken from the west side of the location; crested wheatgrass observed throughout.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 17. Gully erosion occurring on the access road leading to the production areas.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 18. Gully erosion occurring on the access road leading to the production areas.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 19. Unused equipment next to flare unit.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 20. Taken from the reclaimed pit area. The pit area is predominantly undesirable vegetation (e.g. kochia and russian thistle). Additional weed management and reclamation activities are required in order to comply with Rule 1003 standards.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 21. Reclaimed pit area; see comments in Photo 20.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 22. Reclaimed pit area; see comments in Photo 20.

Inspection Photos
Location Name: Castor 36-11-9-59
Location ID: 427480



Photo 23. Reclaimed pit area; see comments in Photo 20.