

Interim Reclamation Inspection

Date: 01/12/2024

Operator: BISON IV OPERATING LLC - 10670

Location ID: 447898

Inspection Document #: 708200882

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 1. Former access road is predominantly weedy vegetation (e.g. kochia and russian thistle) and is not reflective of adjacent reference areas.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 2. Eastern interim areas are predominantly weedy vegetation. Additional reclamation activities are required.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 3. Northern interim areas are predominantly weedy vegetation. Additional reclamation activities are required

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898




Photo 4. Emergency contact information is missing at well signs.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898




Photo 5. Opening/subsidence observed at well API #123-43618.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 6. It doesn't appear that areas not needed for production activities have been reclaimed, illustrated by red polygon. See Photo 7 for additional.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898




Photo 7. Google Earth aerial imagery (circa 11/2023) illustrating that areas not needed for production activities do not appear to have been reclaimed, highlighted with red circle. Approximately 1 acre has not been reclaimed.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 8. Former access road (south of location) is predominantly weedy vegetation (e.g. kochia and russian thistle) and is not reflective of adjacent reference areas.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 9. Eastern interim (south side of location) areas are predominantly weedy vegetation. Additional reclamation activities are required.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898



Photo 10. Topsoil stockpile is predominantly weedy vegetation. Additional reclamation activities are required.

Inspection Photos

Location Name: Anderson Facility 9-59-31 Pad

Location ID: 447898




Photo 11. Google Earth aerial imagery (circa 11/2023) illustrating that darker areas/vegetation represents significant weed cover throughout the interim areas. Additional reclamation activities are required.