

Inspection Photos

Loc: 321012

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/18/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the offsite tank battery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321012 | Date: 1/18/2024

Inspection Photos



Photo 2. Facing toward the tank. There is not secondary containment at the tank.



Inspection Photos



Photo 3. Facing toward the well which is under snow cover.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321012 | Date: 1/18/2024

Inspection Photos



Photo 4. There appears to be vegetative debris at the pumpjack.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321012 | Date: 1/18/2024