

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Jan 17, 2024 at 11:03:59 AM



Jan 17, 2024 at 11:04:04 AM

Photo # 2937 From entrance to location

Photo # 2938 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065




Photo # 2939 Location



Photo # 2940 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 2941 Location




Photo # 2942 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065

Jan 17, 2024 at 11:04:41 AM



Photo # 2943 Location

Jan 17, 2024 at 11:10:20 AM  
CO



Photo # 2944 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 2945 Open ended load line



Photo # 2946 PRV vent line lacks cap