

Inspection Photos

Loc #: 484359

Operator: DESERT EAGLE OPERATING

Inspection Date: 1/18/2024

County: Las Animas



Inspection Photos



Photo 1. Facing east toward the access road standing on County Road 177. There is vehicle rutting and tracking of sediment onto the County Road. BMP's must installed to prevent sediment tracking and road degradation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 1/18/2024

Inspection Photos



Photo 2. Facing east along the access road which is not stabilized. The topsoil of the road is not being protected from degradation. The access road should be seeded and reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 1/18/2024

Inspection Photos



Photo 3. Facing southeast toward the location. All disturbed areas of the location will need to be decompacted and seeded prior to the upcoming growing season.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 1/18/2024

Inspection Photos



Photo 4. Facing southeast toward the well. The sign is laying on the ground not installed.



Inspection Photos



Photo 5. Facing south at the east side of the location. The drill cuttings have been removed but there is still a reddish color in this area that remains which is indicative of the drill cuttings.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 1/18/2024

Inspection Photos



Photo 6. Facing north at the well. There is stained soils near the wellhead that need to be cleaned up..

