

Inspection Photos

Loc #: 481115

Operator: DESERT EAGLE OPERATING

Inspection Date: 1/18/2024

County: Las Animas



Inspection Photos



Photo 1. Facing southeast toward the access road to the Red Rocks #1-13 drill site. There is some signs rutting occurring onto the County Road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 2. Facing southeast along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 3. Facing southeast along the access road on right side. This area has been widened and disturbed due to vehicle turning.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 4. Facing southeast toward the Red Rocks #1-13 drill site. There is an unpermitted road cutting across the location to the processing plant. Vehicle must stay on designated access road boundary only.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 5. Facing southeast toward the well with sign posted at the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 6. Facing southeast toward the flowline disturbance. It appears disturbed soils have been seeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 7. Facing south at the location. The excavated area at the wellhead has been backfilled and the rock debris has been removed. It is unknown what topsoil material was replaced since it was not properly salvaged. It does not appear soil closer to the well were seeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 481115 | Date: 1/18/2024

Inspection Photos



Photo 5. There is an open excavation at the wellhead and topsoil was not salvaged and protected. The open excavation at the wellhead and flowlineshow be properly marked/fenced to prevent livestock/wildlife entry.



Inspection Photos



Photo 6. Facing east toward the flowline disturbance. Loose soils are susceptible to erosion and need to be stabilized.



Inspection Photos



Photo 7. Standing further east of the location facing west along the flowline. Loose soils are susceptible to erosion and need to be stabilized.

