


Inspection Photos

Location: Riverton 14-21 and Riverton 14-21 TR

Facility ID: 333395



Jan 19, 2024 at 9:59:44 AM
+37.238988, -104.684769
ECMC



Jan 19, 2024 at 10:01:12 AM
+37.239086, -104.684783
ECMC

Photo 1 –Well Site Placard

Photo 2 – Well location looking south



Inspection Photos
Location: Riverton 14-21 and Riverton 14-21 TR
Facility ID: 333395



Photo 3 – TR Well location looking North

Photo 4 – KV Wellhead looking south

Inspection Photos
Location: Riverton 14-21 and Riverton 14-21 TR
Facility ID: 333395



Photo 5 – Spill Start

Photo 6 – Spill path looking Northeast

Inspection Photos

Location: Riverton 14-21 and Riverton 14-21 TR

Facility ID: 333395



Photo 7 – Point along spill path

Photo 8 – Looking to spill endpoint

Inspection Photos
Location: Riverton 14-21 and Riverton 14-21 TR
Facility ID: 333395



Photo 9 – Electric Compressor with oil diapers in skid pan.