

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2024

Submitted Date:

01/23/2024

Document Number:

710500160**FIELD INSPECTION FORM**Loc ID 308547 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273665	WELL	PR	04/15/2005	CBM	071-08204	FRIO CANYON 31-35	EI
308547	LOCATION	AC			-	FRIO CANYON-631S66W 35NWNE	EI

General Comment:

This is an Environmental Inspection for the Frio Canyon 31-35 Active well Location, Location Id 308547 Located in Las Animas County Colorado.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	At the time of inspection tall grass was observed around the wellhead and inside the sound panel building.		
Corrective Action:	Comply with Rule 606.		Date: 02/14/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Other	Separator			
Comment:	At the time of inspection, oily material was noted adjacent to the Meter House and along the bottom of the skid. Operator shall investigate the area to determine where the oily substance is originating. Operator shall file a Form 19 Per Rule 912.			
Corrective Action:	Comply with Rule 912.			Date: 01/24/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Compressor	# 1		corrective date
Comment:	At the time of inspection there was oily water observed in the bottom of the Engine Skid.		
Corrective Action:	Comply with Rule 608.e.		Date: 01/31/2024
Type: Prime Mover	# 1		
Comment:	At the time of inspection there was oily water observed in the bottom of the Engine Skid.		
Corrective Action:	Comply with Rule 608.e.		Date: 02/14/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	273665	Type:	WELL	API Number:	071-08204	Status:	PR	Insp. Status:	EI
Facility ID:	308547	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500161	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403957