

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2023

Submitted Date:

01/23/2024

Document Number:

699805736

FIELD INSPECTION FORM

Loc ID: 325573 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10254
Name of Operator: RED MESA HOLDINGS/O&G LLC
Address: 5619 DTC PARKWAY - STE 800
City: GREENWOOD State: CO Zip: 80111

Contact Information:

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaolo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215027	WELL	PR	09/30/2010	GW	067-06632	HERRERA 4 (OWP)	PA

General Comment:

ECMC Inspection Report Summary
On 11/10/2023 I, OWP Specialist Corey DePaolo, Witnessed the plugging and abandonment of the RED MESA HOLDINGS/O&G LLC HERRERA-N33N12W/26NWNE (OWP) Location #325573 La Plata County Colorado.

-OWP Plugging operations consisted of setting 5 plugs over the course of 5 days. Three CICR, one balance plug and surface. The well was cut and capped on 11/10/2023.

This is a summary of the inspection report

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	All signs have been removed from location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Other	#		
Comment:	All equipment has been removed from location		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215027 Type: WELL API Number: 067-06632 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 3233' to 0'

Cement Volume (sx): 210

Good Return During Job: YES

Cement Type: Prem G

Comment: OWP Plugging operations consisted of setting 5 plugs over the course of 5 days. Three CICR, one balance plug and surface. The well was cut and capped on 11/10/2023.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Related Facility for comments	depaoloc	01/23/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805737	Photo log Insp. #699805736	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6403944