

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2024

Submitted Date:

01/23/2024

Document Number:

708902869**FIELD INSPECTION FORM**Loc ID 334682 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:25 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286066	WELL	PR	09/01/2022	GW	045-12603	FEDERAL 20-10 (PN20)	PR
286631	WELL	PR	09/01/2022	GW	045-12713	FEDERAL 20-12(PN20)	PR
413026	WELL	PR	07/12/2011	GW	045-18708	Federal 20-11 (PN20)	PR
413029	WELL	PR	07/12/2011	GW	045-18711	Federal 20-14BB (PN20)	PR
415750	WELL	PR	07/12/2011	GW	045-19158	Federal Gardner 20-7 (PN20)	PR
415795	WELL	PR	07/12/2011	GW	045-19163	Federal Gardner 20-7BB (PN20)	PR
415799	WELL	PR	07/12/2011	GW	045-19164	Federal Gardner 20-6 (PN20)	PR

General Comment:**CECMC Inspection Report Summary**

On 01/23/2024 at approximately 11:17 hours, I, Compliance Specialist, Wayne Smelser
Conducted a follow up inspection at CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad.
Location # 334682 in Garfield County Colorado.

Please refer to inspection 707800571 conducted on 08/28/2023, previous corrective actions have been completed.
Location is within High Priority/Density/Black Bear Habitat areas.
Location is in close proximity to Rule 411a Surface Water External Buffer.
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife with a CA date of 01/30/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Thrust blocks & jersey barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	01/30/2024
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	286066	Type:	WELL	API Number:	045-12603	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	286631	Type:	WELL	API Number:	045-12713	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	413026	Type:	WELL	API Number:	045-18708	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	413029	Type:	WELL	API Number:	045-18711	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415750	Type:	WELL	API Number:	045-19158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415795	Type:	WELL	API Number:	045-19163	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	415799	Type:	WELL	API Number:	045-19164	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						Sparse to none in some areas
		Culverts				
		Ditches				
		Compaction				Light compaction in sections
Compaction						Small areas of light compaction
		Gravel				Sparse to none in visible sections

Comment: Limited Stormwater inspection due to snow.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	01/23/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902870	Inspection 708902869 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6404391
708902871	Inspection 708902869 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6404392