

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/24/2024

Submitted Date:

01/24/2024

Document Number:

702402953

**FIELD INSPECTION FORM**

Loc ID 318232 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240933	WELL	PR	10/01/2023	OW	123-08721	UPRR 42 PAN AM AE 1	SI

**General Comment:**

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil approx. 15 ft. from the WH		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes in compliance with Rule 1002..(2).D.		Date: <u>01/31/2024</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	fabricated angle iron & chainlink topped with barb wire.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panel, meter box and transformers		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	electric motor		

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240933 Type: WELL API Number: 123-08721 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI valves are closed on the WH and the electric panel is shut off.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Tuesday 1-24-2024 at approximately 1400 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: KP Kauffman                      Location name:                      Location ID #318233                      Well Name: UPRR 42 Pan Am AE 1                      API # 05-123-08721                      County: Weld                      Weather: Overcast.                      Location: Dry.                      While there, I observed a wellsite, SI at the time of the inspection.                      During this inspection, I observed the following possible compliance issues:                      1002..(2).D Housekeeping: CA date 1-31-2024                      See attached photos.                      A follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with ECMC rules.</p>	revasr	01/24/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402954	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405661">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405661</a>