

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Battery sign lacks a current operator emergency contact number, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.e.		Date: 02/29/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment: DCP calibration card is current.		Date:
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Bradenhead valve is exposed at surface.		
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment: Automation array and two ECD scrubbers		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Lined berm				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	<100 BBLS	BV CONCRETE		,
Comment: 60 bbls					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Lined berm					
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 417532 Type: WELL API Number: 123-31689 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 01/31/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/25/2024 at approximately 12:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Kissler K21-21D location #416874 in Weld County, Colorado. While there, I observed that the battery sign lacked an emergency contact number. During this inspection the following possible compliance issues were observed: Rule 605.e. with a corrective action date of 2/29/2024. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	01/25/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697008803	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6407208