

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2024

Submitted Date:

01/19/2024

Document Number:

713600635**FIELD INSPECTION FORM**Loc ID 321012 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments8 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Kelly, George	(888) 858-7886	envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479904	TANK BATTERY	AC	05/04/2021		-	Hefley Tank	RI

**General Comment:**

This is a follow up of the previous reclamation inspections.  
See attached photos and additional details within this report.

The corrective actions of the previous inspections have not been completed.  
Operator is directed to perform corrective actions outlined on this inspection report immediately

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	A sign is posted on the backside of the tank battery which is not readily visible and has incomplete information. Another sign was installed on the front of the meter shed but is faded and not legible. The sign did not provide the following: Sign did not measure between 3 and 6 square feet. No phone number for local emergency services, public road used to access the site, or the legal location including the quarter quarter section. Previous corrective action has not been completed.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 09/14/2019
Type	WELLHEAD		
Comment:	There was a sign posted at the wellhead but is not legible. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 09/14/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There is vegetative debris on the pumpjack which is a fire hazard.		
Corrective Action:	Comply with Rule 606 Remove debris		Date: 06/30/2021
Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment and debris at the tank battery and meter shed location		
Corrective Action:	Comply with Rule 606 Remove unused equipment and debris		Date: 09/14/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	The fencing around the pumpjack is in disrepair. The gate was observed on the ground near the wellhead.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: 06/22/2020

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Meter run is 575' East of wellhead. The meter shed is leaning and unstable sitting on wood blocks. This is a safety concern. Erosion has occurred underneath the meter shed making it unstable. Corrective action has not been performed.		
Corrective Action:	Properly stabilize and secure meter shed. This is a safety issue and a good housekeeping requirement. Comply with Rule 606.		Date: 09/14/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS			,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	There is no secondary containment around the tank. If the tank is unused then it must be removed. Corrective action has not been performed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1). Comply with Rule 210.				Date: 09/14/2019

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion issues at the meter shed/tank battery site. The location is not stabilized. Corrective action has not been performed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 09/14/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403660991	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400254">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400254</a>
713600637	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6400251</a>