



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Pumping unit electric motor (prime mover), and service meter removed		
Corrective Action:	Comply with Rule 606	Date:	02/28/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety gaurds		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electrical disconnect, metal panels		
Corrective Action:		Date:	

**Equipment:**

Type	Equipment ID	Comment	Corrective Action	Date	corrective date
Prime Mover	# 0	REMOVED			
Pump Jack	# 1	UNUSED EQUIPMENT			
Bradenhead	# 1	piped to surface			
Ancillary equipment	# 2	electrical disconnect, service meter removed			

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 242406 Type: WELL API Number: 123-10197 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_  
 Comment: Valves appeared to be closed at time of inspection  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/06/2023 Annual Brhd Completed? Yes  
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      On Monday 1-22-2024 at approximately 13:00, I, Inspector Michael Kester, conducted an on-site reinspection as per Doc #699504995.                      Location: UPRR42 PanAm AU 1                      Operator: KPK                      API#: 123-10197                      County: Weld                      While there, I observed well site with pumping unit.                      At time of inspection it does appear corrective actions from previous inspection have been address Doc # 699504995. Now with overgrown vegetation cleared, Pumping unit is unusable equipment with electrical meter and motor removed.                      Unused equipment, Rule 606, corrective action date 2-28-2024 photo 3, &amp; 4                      Weather conditions: sunny and dry                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	01/22/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403662620	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6402442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6402442</a>
713300549	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6402441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6402441</a>