

Inspection Photos
UPRR 50 Pan Am D-1 Flowline Spill
Spill ID 482826



Photo 1 – Open excavation



Photo 2 - Open excavation



Inspection Photos
UPRR 50 Pan Am D-1 Flowline Spill
Spill ID 482826



Photo 3 – Open excavation



Photo 4 - Open excavation

Inspection Photos
UPRR 50 Pan Am D-1 Flowline Spill
Spill ID 482826



Photo 5 – Open excavation



Photo 6 - Former E&P Waste area

Inspection Photos
UPRR 50 Pan Am D-1 Flowline Spill
Spill ID 482826



Photo 7 – Former E&P Waste area



Photo 8- Former E&P Waste area



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
UPRR 50 Pan Am D-1 Flowline Spill
Spill ID 482826



Photo 9 – Former E&P Waste area



Photo 10 - Former E&P Waste area. Holes in lining.