

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

01/30/2024

Document Number:

699805754**FIELD INSPECTION FORM**Loc ID 325542 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
De Paolo, Corey		corey.depaolo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214977	WELL	PR	01/01/2011	OW	067-06582	TURNER 3 (OWP)	PA

General Comment:[ECMC Inspection Report Summary](#)[On 10/27/2023 I, OWP Specialist Corey DePaolo,](#)[Witnessed the plugging and abandonment of the RED MESA HOLDINGS/O&G LLC TURNER-N33N12W/26NENW \(OWP\)](#)[Location #325542 La Plata County Colorado.](#)[-OWP Plugging operations consisted of setting 3 plugs over 4 days. Two CICR and surface. The well was cut and capped on 10/27/2023.](#)[This is a summary of the inspection report](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	All signs have been removed from location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	All equipment has been removed from location		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER					
Comment:	Tank battery has been removed from location				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214977	Type:	WELL	API Number:	067-06582	Status:	PR	Insp. Status:	PA
Cement									
Cement Contractor									
Contractor Name: Delsco					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range): 3308' to 0'					Cement Volume (sx): 260				
Good Return During Job: YES					Cement Type: Prem G				
Comment:					OWP Plugging operations consisted of setting 3 plugs over 4 days. Two CICR and surface. The well was cut and capped on 10/27/2023.				
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Related Facility for comments	depaoloc	01/30/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805755	Photo log Insp. #699805754	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6411953