

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/24/2024

Submitted Date:

01/30/2024

Document Number:

709100208

FIELD INSPECTION FORM

Loc ID 312229 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

6 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Alex Fischer		alex.fischer@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	All Inspections
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	
Dylan Edwardson		dylan.edwardson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219734	WELL	PR	06/15/2003	OW	075-06964	PROPST B3X	EI
312229	LOCATION	AC			-	PROPST-611N53W 27SESE	EI
479469	TANK BATTERY	AC	02/23/2021		-	Propst B3X	EI

General Comment:

On January 24, 2024, ECMC Environmental Staff Krystal Heibel, Alex Fischer, and Dylan Edwardson conducted an environmental field inspection of Western Operating Company (Western) Probst B3X (Location ID: 312229).

Weather was sunny and temperature about 30 degrees Fahrenheit. Refer to Interim Reclamation and Stormwater Inspection Report (Doc #708200896) for additional information.

The following is a summary: Pit Facility ID 100312 is not in use.

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) and corrective action due dates from previous inspections that have not been addressed are still applicable.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard at vertical separator not legible (e.g. cracked, peeling, faded).		
Corrective Action:	Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.		Date: <u>11/27/2023</u>
Type	TANK LABELS/PLACARDS		
Comment:	Buried vessel located east of pit facility ID 100312 is not labeled.		
Corrective Action:	Comply with Rule 605.e.g. and h.		Date: <u>01/24/2024</u>
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment stored next to tank battery		
Corrective Action:	Comply with Rule 606		Date: <u>01/24/2024</u>
Type	TRASH		
Comment:	Trash and debris (buckets, wire, bottles, pipe) observed throughout location.		
Corrective Action:	Comply with Rule 606 and remove all trash and debris from location. The location will remain out of compliance until the corrective action has been resolved.		Date: <u>01/24/2024</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil		<= 1 bbl	
Comment:	Stained soil observed near exhaust at pumpjack, wellhead, at tank battery valve/fitting, within the pit, at the truck loadout, next to the heater treater, within the metal shed, and throughout the location (including stained soil northwest of wellhead). Refer to previous inspection report (Doc# 708200708) for information.		
Corrective Action:	Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.		Date: <u>11/27/2023</u>
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	#		corrective date
Comment:	Valves near the wellhead and at the tank battery were dripping, and valves near the metal shed were not plugged.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>01/24/2024</u>
Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 219734 Type: WELL API Number: 075-06964 Status: PR Insp. Status: EI

Facility ID: 312229 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 479469 Type: TANK API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100209	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6412973