

Inspection Photos
Location Name: Lundvall 13-13
Location ID:329427



Energy & Carbon Management Commission
40.40552, -104.84135, 1464.2m, 145°
01/30/2024 10:36:42

Production facility



Energy & Carbon Management Commission
40.40068, -104.84004, 1469.6m, 172°
01/30/2024 10:44:55

Wellhead