

Storm Water Management and Erosion control

Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad

Location #: 334182



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 235 yards from Spring Creek.

Section/Township/Range: 1 8S96W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4818 Location



Photo # 4819 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4820 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4821 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Jan 30, 2024 at 11:43:43 AM
CO

Photo # 4822 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Jan 30, 2024 at 11:44:19 AM
CO

Photo # 4823 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4824 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4825 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4826 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4827 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4828 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4829 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4830 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4831 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4832 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4833 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4834 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4835 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4836 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4837 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4838 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4839 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4840 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4841 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC MURRAY-68S96W 1SWSW Pad
Location #: 334182



Photo # 4842 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)



Photo # 4843 Insufficient tracking BMP's/tracking off location & onto to CR 306 (Spring Creek RD)