

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2024

Submitted Date:

01/24/2024

Document Number:

695109066**FIELD INSPECTION FORM**Loc ID 322215 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|----------------------|---------------------------------|
| Javernick, James | 719-275-3040/719-671-3787 | javernick1@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 209871 | WELL | PR | 01/01/2020 | OW | 043-05088 | TEMPLETON 1 | PR |

General Comment:

THIS IS A FACILITY AND SURFACE EQUIPMENT INSPECTION. ANY CORRECTIVE ACTIONS FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: CATTLE PANEL

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Other

#

Comment: WELLHEAD IS LEAKING SEE ATTACHED FLIRR CAMERA VIDEO

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 01/25/2024

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | | STEEL AST | | 38.334498,-105.111074 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

Condition

Other (Content)

Other (Capacity) 210 BBL

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | | | |
|--------------------|----------|-----------------|-----------------|----------|-------|
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|-------|--|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

Flaring:

| | | | |
|--------------------|-------|--|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

| Inspected Facilities | | | | | | | | | |
|-------------------------|--------|----------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 209871 | Type: | WELL | API Number: | 043-05088 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | | Annual Brhd Completed? | | | | | | | |
| Last Brhd Test Results | | Initial Surf Csg Pressure: | | Fluid Type: | | | | | |
| | | End Surf Csg Pressure: | | | | | | | |
| Comment: | | SUBMIT REPORTS | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403665868 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405920 |
| 695109067 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405914 |
| 695109068 | FLIR VIDEO | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405915 |