



FORM
INSP

Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/22/2024

Submitted Date:
01/24/2024

Document Number:
708301576

FIELD INSPECTION FORM

Loc ID
334114

Inspector Name:
Morris, Matthew

On-Site Inspection ☐

2A Doc Num:

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☒ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293844	WELL	PR	12/04/2007	GW	045-15137	SPECIALTY RESTAURANTS SG 11-35	PR
293853	WELL	PR	12/05/2007	GW	045-15138	SPECIALTY RESTAURANTS SG 21-35	PR
293854	WELL	PR	12/05/2007	GW	045-15139	SPECIALTY RESTAURANTS SG 321-35	PR
293855	WELL	PR	12/05/2007	GW	045-15140	SPECIALTY RESTAURANTS SG 421-35	PR
293856	WELL	PR	12/05/2007	GW	045-15141	SPECIALTY RESTAURANTS SG 521-35	PR
293857	WELL	PR	12/05/2007	GW	045-15142	SPECIALTY RESTAURANTS SG 311-35	PR
293858	WELL	PR	12/05/2007	GW	045-15143	SPECIALTY RESTAURANTS SG 411-35	PR
293859	WELL	PR	05/31/2008	GW	045-15144	SPECIALTY RESTAURANTS SG 511-35	PR

General Comment:

COGCC Inspection Report Summary

On 1/22/2024 at approximately 10:05, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, SPECIALTY RESTAURANTS-67S96W/35NWNW at Location ID #334114 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) Open-ended load line on produced water tank

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Date Run: 1/31/2024 Doc [#708301576]

Page 1 of 6

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 285-9377

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 8		corrective date
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	STEEL AST		,	
Comment:	Open-ended load line on tank.					
Corrective Action:	Secure load line to comply with Rule 608.e.					Date: 01/31/2024

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293844	Type:	WELL	API Number:	045-15137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293853	Type:	WELL	API Number:	045-15138	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293854	Type:	WELL	API Number:	045-15139	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293855	Type:	WELL	API Number:	045-15140	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293856	Type:	WELL	API Number:	045-15141	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293857	Type:	WELL	API Number:	045-15142	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293858	Type:	WELL	API Number:	045-15143	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	293859	Type:	WELL	API Number:	045-15144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Compaction						
Gravel						
Tracking Pad						
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403665870	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405944
708301577	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405941