

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 5391 From entrance to location



Photo # 5392 From entrance to location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 5393 Location



Photo # 5394 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065




Photo # 5395 Location



Photo # 5396 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065




Photo # 5397 Location



Photo # 5398 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Feb 1, 2024 at 3:00:24 PM  
CO

Photo # 5399 Location



Feb 1, 2024 at 3:00:09 PM  
CO

Photo # 5400 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



**Photo # 5401 Stained soils & snow**



**Photo # 5402 Stained soils & snow**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 5403 Staining in snow



Photo # 5404 Stained soils & snow

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 5405 Stained soils & snow



Photo # 5406 Stained soils & snow



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



**Photo # 5407 Stained soils & snow**



**Photo # 5408 Stained soils & snow**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 28-15X (PJ28) Pad

Location #: 334065



Photo # 5409 Possible tear in base of secondary containment liner



Photo # 5410 Possible tear in base of secondary containment liner