

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is in close
proximity to Rule 411a Surface Water External Buffer.**

Section/Township/Range: 20 7S95W



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5000 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5001 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5002 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5003 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5004 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5005 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5006 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5007 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5008 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5009 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5010 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5011 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5012 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5013 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5014 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5015 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682




Photo # 5016 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5017 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5018 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5019 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5020 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5021 Lack of stabilization/compaction/insufficient BMP's on lease road

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 5022 Lack of stabilization/compaction/insufficient BMP's on lease road



Photo # 5023 Lack of stabilization/compaction/insufficient BMP's on lease road