

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 4988 From entrance to location



Photo # 4989 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad

Location ID: 334682



Photo # 4990 Location



Photo # 4991 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad

Location ID: 334682



Photo # 4992 Location



Photo # 4993 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad
Location ID: 334682



Photo # 3518 From inspection 708902869 conducted on 01/23/2024 Flowline heating insulation open ended/ wildlife hazard/available for entry by wildlife

Photo # 4994 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad

Location ID: 334682



Photo # 4995 Rupture disc vent line lacks cap

Photo # 4996 Rupture disc vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 20-10 (PN20) Pad

Location ID: 334682



**Photo # 4997 Barbed wire laying on ground/wildlife hazard
(N/NW area on edge of location)**



**Photo # 4998 Barbed wire laying on ground/wildlife hazard
(N/NW area on edge of location)**